Metallurgical
Laboratories Chemists Assayers Spectographers
1717 Solano Way #39 Concord, CA 94520 Tel 925-603-1080 FAX 925-603-108

Submitted By: LunchBots, Inc.
555 Bryant St.,Ste 214
Palo Alto, CA. 94301

Date: 08/06/09

Sample of: Alloy

Lab# 1902

Sample Mark	
Lunch Box Blue Lid	Analyses of all eight samples show them to be manufactured
Container no divider	from 300 series Stainless Steel*
Lunch Box Orange lid	
Container with divider	No Lead was detected in any sample. **
Lunch Box Yellow Lid	
Container with divide	
Lunch Box Green Lid	
Container no divider	
	* All samples were tested using an Oxford Instruments
	ED2000 X=Ray Florescence Spectrometer using
	A "US Bureau of Standards" 300 Series Stainless
	Steel Standard.
	** Lead detection levels are less than 0.000001%
	Or the equivalent of less than 0.1 Parts per million.

Metallurgical Labs

By